



Vendors Report (Building & Termite/ Timber Pest)

Inspection Date: 1 Oct 2020

Property Address: Bundoora



Contents

Inspection details	3
General description of property	4
Accessibility	7

Property Inspection Report

Summary	10
Significant items	11
Additional comments	75
Conclusion	92

Timber Pest Inspection Report

Summary	95
Significant items	96
Conclusion	115
Risk management options	115
Definitions to help you better understand this report	116
Terms on which this report was prepared	118

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

Inspection details

Property Address: Bundoora

Date: 1 Oct 2020

Report Type: Property and Timber Pest Report

Client

Name: Private

Email Address:

Phone Number:

Consultant

Name: Les Camilleri

Email Address: les@masterpropertyinspections.com.au

Licence / Registration Number: A25361

Company Name: Master Property Inspections

Company Address: Essendon Victoria 3040

Company Phone Number: 03 93373884

General description of property

Building Type:	Detached house
Number of Storeys:	Single storey
Smoke detectors:	2 fitted, but not tested IMPORTANT NOTE - The adequacy and testing of smoke detectors is outside the scope of this standard inspection and report. Accordingly, it is strongly recommended that a further inspection be undertaken by a suitably qualified person.
Siting of the building:	Not Applicable
Gradient:	The land is sloping
Site drainage:	The site appears to be poorly drained in areas as stated in the report.
Access:	Not Applicable
Occupancy status:	Unoccupied
Furnished:	Unfurnished
Strata or company title properties:	No
Orientation of the property:	The facade of the building faces northwest Note. For the purpose of this report the façade of the building contains the main entrance door.
Weather conditions:	Dry

Primary method of construction

Main building – floor construction:	Concrete Stumps, Brick foundation walls
-------------------------------------	---

Main building – wall construction:	Internal gypsum plasterboard, Brick veneer (timber framed)
Main building – roof construction:	Timber framed, Pitched roof, Finished with roofing tiles
Other timber building elements:	Architraves, Various other timbers in many areas., Skirting, Doors, Timber In Garden, Floor Boards , Window frames
Other building elements:	Carport
Overall standard of construction:	Acceptable
Overall quality of workmanship and materials:	Acceptable
Level of maintenance:	Reasonably maintained

Special conditions or instructions

Special requirements, requests or instructions given by the client or the client's representative -

There are no special conditions or instructions

Inspection agreement

AS 4349.1-2007 and 4349.3-2010 require that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building and which is in reasonable condition, having been adequately maintained over the life of the building. This means that building being inspected may not comply with Australian Standards, building regulations or specific state or territory requirements applicable at the time of the inspection

Inspection agreement supplied: No

Terminology

The definitions below apply to the types of defects associated with individual items / parts or inspection areas -

Damage	The building material or item has deteriorated or is not fit for its designed purpose
Distortion, warping, twisting	The item has moved out of shape or moved from its position
Water penetration, Dampness	Moisture has gained access to unplanned and / or unacceptable areas
Material Deterioration	The item is subject to one or more of the following defects; rusting, rotting, corrosion, decay
Operational	The item or part does not function as expected
Installation	The installation of an item is unacceptable, has failed or is absent

Scope of inspection

BUILDING INSPECTION

This is a visual Building Inspection Report carried out in accordance with AS4349.1 -2007. The purpose of this inspection is to provide advice to the Client regarding the condition of the Building & Site at the time of inspection. The report covers only safety hazards, major defects, and a general impression regarding the extent of minor defects. The building was compared with a building that was constructed in accordance with the generally accepted practice at the time of construction and which has been maintained such that there has been no significant loss of strength and serviceability.

TIMBER PEST INSPECTION

This Visual Timber Pest Inspection & Report is in accordance with Australian Standard 4349.3 -Inspection of Buildings Part 3: Timber Pest Inspections. This Report only deals with the detection or non-detection of Timber Pest Attack and Conditions Conducive to Timber Pest Attack discernible at the time of inspection. The inspection was limited to the Readily Accessible Areas of the Building & Site and was based on a visual examination of surface work (excluding furniture and stored items), and the carrying out of Tests.

Accessibility

Unless noted in “Special Conditions or Instructions”, the inspection only covered the Readily Accessible Areas of the Building and Site (see Note below).

Note. With strata and company title properties, the inspection was limited to the interior and the immediate exterior of the particular residence inspected. Common property was not inspected.

“Readily Accessible Areas” means areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term ‘readily accessible’ also includes:

(a) accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the area is not more than 2 metres from a point with conforming clearance (i.e. 400 mm high by 600 mm wide); and

(b) areas at the eaves of accessible roof spaces that are within the consultant’s unobstructed line of sight and within arm’s length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).

“Building and Site” means the inspection of the nominated residence together with relevant features including any car accommodation, detached laundry, ablution facilities and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth, embankments, surface water drainage and stormwater run-off within 30 m of the building, but within the property boundaries.

For the Timber Pest Report, the term “Building and Site” is extended to include the main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees and stumps with a diameter greater than 100 mm and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).

The inspection did not include areas, which were inaccessible, not readily accessible or obstructed at the time of inspection. Areas, which are not normally accessible, were not inspected and include - but not limited to - the interior of a flat roof or beneath a suspended floor filled with earth. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder’s debris, vegetation, pavements or earth.

Areas Inspected

The inspection covered the Readily Accessible Areas of the property

- The site
- Building exterior
- Building interior
- Subfloor In Part
- Roof Space - ONLY Partial
- The Site
- Limited Areas
- As stated in this report.

Areas not inspected

The inspection did not include areas, which were inaccessible, not readily accessible or obstructed at the time of inspection. The Consultant did not move or remove any obstructions which may be concealing evidence of defects. Areas, which are not normally accessible, were not inspected. Evidence of defects in obstructed or concealed areas may only be revealed when the items are moved or removed or access has been provided.

Obstructions and Limitations

The following obstructions may conceal defects:

- Thick foliage
- Vegetation
- Above safe working height.
- Appliances and equipment
- Landscaping abutting the building
- Earth abutting the building
- Flooring
- Ceilings
- Built-in cupboards
- Paved areas abutting the building
- Insulation In Roof Space
- Insulation

Obstructions increase the risk of undetected defects, please see the overall risk rating for undetected defects.

Inaccessible Areas

The following areas were inaccessible:

- Subfloor part
- Roof Space WAS NOT INSPECTED
- Roof Space
- Exterior roof in part

Undetected defect risk assessment

Due to the level of accessibility for inspection including the presence of obstructions, the overall degree of risk of undetected structural damage and conditions conducive to structural damage was considered:

HIGH

A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This will involve a separate visit to the site, permission from the owner of the property and additional cost.

Unless stated otherwise, any recommendation or advice given in this Report should be implemented as a matter of urgency.

Summary

SUMMARY INFORMATION: The summary below is used to give a brief overview of observations made in each inspection area. The items listed in the summary are noted in detail under the applicable sub headings within the body of the report. The summary is NEVER to be relied upon as a comprehensive report and the client MUST read the entire report and not rely solely on this summary. If there is a discrepancy between the information provided in this summary and that contained within the body of the Report, the information in the body of the Report shall override this summary. (See definitions & information below the summary to help understand the report)

Evidence of Serious Safety Hazards	Found
------------------------------------	-------

Evidence of Major Defects	Found
---------------------------	-------

Evidence of Minor Defects	Found
---------------------------	-------

Additional specialist inspections

It is Strongly Recommended that the following Inspections and Reports be obtained prior to any decision to purchase the Property and/or before settlement. Obtaining these reports will better equip the purchaser to make an informed decision.

- As identified in the summary and the defect statements in this report.
- Termite & Timber Pest Technician / Licensed Pest Controller

Significant items

The following items and matters were reported on in accordance with the Scope of Inspection. For building elements not identified in this Condition Report, monitoring and normal maintenance must be carried out (see also Section G 'Important note').

Serious Safety Hazard

Serious Safety Hazard 1.01

Location: The Site

Finding: No Smoke Detectors - Installation Required.
Reporting on Smoke Detectors or Alarms, including hard wired smoke detection systems and their legislative requirements, is outside the Scope of this Report.

Please note that this defect is highlighted as a caution only. We suspect, based on our experience in the building industry, that the absence of smoke detectors should be addressed as a matter of urgency to improve occupant safety.

Locations with the red arrows indicates the locations that we suggest smoke detectors should be installed, which is outside bedroom doors and at the bottom and top of stair cases.

Further Inspection and/or advisory services is necessary to provide advice on the sufficiency, type and location of smoke detectors, and to test the functionality of all devices. Greater requirements for fire safety and detection exist for commercial buildings.

Always ensure sufficient working and suitable smoke detectors are installed prior to occupying any building. Additionally, it is advised that all smoke detectors be tested by the homeowner on a monthly basis.

Please refer to AS3786 and state based legislation, which may also apply.

A qualified electrician is required do these works for hard wiring.

Upon completion a safety certificate is required to be supplied to the owner of the building.



Serious Safety Hazard 1.02

Location: Internal Areas

Finding: Asbestos - Suspected ACM Identified On Site.
IMPORTANT: The Australian Standards for Pre-Purchase building inspections (AS 4349.1-2007) does not require Asbestos inspections in a report, however Master Property Inspections trained inspectors add this bonus service, as we feel that Asbestos is a very important topic that our clients should have an awareness of.

Asbestos in the older homes can be in the glue adhesive behind the wall tiles or floor tiles, Asbestos can be behind the wall tiles and floor tiles in relation to the cement sheet or the tile backing.

Asbestos can be in the old wardrobes and cupboard areas, asbestos can be in the flu systems of the old hot water services or heater flu systems. Asbestos can be on the walls or ceilings. Asbestos can be in the eaves in the older homes and the exterior walls of the older homes. Asbestos can be found in the roof space areas in the floor space areas and in the old sheds.

This is only the typical type scenarios in the homes up to 1990 in particular.

Whilst we are including in this report areas that we suspect is Asbestos, it is important to note that this report in relation to asbestos is a GUIDE ONLY and we do not guarantee that there are no other areas at this property that may contain Asbestos (ACM)

Reporting on Asbestos is outside the Scope of this Report. This suspected defect is highlighted as a caution ONLY and is ONLY a guide as asbestos inspections are outside the scope of pre-purchase inspection and reports.

We suspect, based on our experience in the building industry, that there is a higher risk of the identified building element containing asbestos (ACM).

Areas with the red arrows, have a high potential of containing asbestos (ACM). When a red arrow points at a tile for example, the asbestos material may be in the tile, the tile glue and/or the tile backing sheet.

As Asbestos Reporting is outside the scope of this report, we advise that you consider a separate Asbestos Inspection and Condition Audit, which can include the taking of samples for definitive confirmation of the presence of Asbestos.

In the interim, the client is advised to act with caution, especially when considering any damage to building materials general wear and tear renovations extensions demolition and general maintenance activities due to the suspected presence of Asbestos.

PLEASE NOTE : We are able to perform an Asbestos Inspection and Condition Audit, which can include the taking of samples for definitive confirmation of the presence of Asbestos. This inspection as noted above is outside the scope of this inspection but at request of the client we can perform the necessary inspection and take the samples to the laboratory to give you a comprehensive and definitive inspection report, with laboratory results.



Serious Safety Hazard 1.03


Location: Electrical Works & Materials



Finding: Electrical - Switch - Damaged/Faulty

The switches in areas were found to be damaged or faulty at the time of inspection. This occurs generally when the building materials have either aged and decayed or as a result of impact damage (accidental or deliberate).

Repair and/or replacement of the switch is advised to ensure the fixture and it's associated structures are safe and fully operational. A licensed electrician should be appointed to repair/replace the light switch as soon as possible.

Please engage a licensed electrician to further inspect the property for the repairs and replacements as required.





Serious Safety Hazard 1.04



Location: Electrical Works & Materials

Finding: Electrical - Power Points - Damaged/Faulty

The power points in areas were found to be damaged or faulty at the time of inspection. This occurs generally when the building materials have either aged and decayed or as a result of impact damage (accidental or deliberate).

Repair and/or replacement of the power points is advised to ensure the fixture and it's associated structures are safe and fully operational. A licensed electrician should be appointed to repair/replace the power points as soon as possible.

Please engage a licensed electrician to further inspect the property for the repairs and replacements as required.



Serious Safety Hazard 1.05

Location: Mould In Caulking / Silicone-All Wet Areas

Finding: Mould In Caulking / Silicone

Mould in caulking or silicone is generally caused by faulty and/or damaged caulking or silicone as the moisture and water ingresses into the caulking or silicone.

The caulking or silicone must be replaced and the areas are cleaned and new caulking or silicone applied.

A handyman or professional, such as a tiler, plumber, builder or there are professional caulkers who take the old caulking or silicone out and re-install new products to all the junction areas.

Generally, the client is advised to ensure that the general environment is free of moisture and humidity to aid in the prevention of mould formation and development. Any mould found during the inspection should be cleaned immediately and/or taken out, particularly where the mould is in the silicon / caulking.

Where mould is particularly serious cleaning or remediation works should be performed by a cleaning contractor.

Please note that severely affected building elements may require replacement by a registered builder or qualified carpenter, however generally where mould is found in bathrooms benches, shower tile junctions, laundry sinks and all other wet area junctions you can get rid of the mould, once you take out the old caulking in most cases.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





Serious Safety Hazard 1.06

Location: Windows - Internal Areas

Finding: Window - Binding / Jamming / Out Of Level
Binding, Jammed, Jamming and/or Out Of Level Windows is evident during standard operation.

Several windows throughout the property were jammed and difficult to operate at the time of the inspection. Windows provide ventilation to the adjoining area and should be at a fully operational level to ensure user comfort. Restricted function of the window may also pose as a potential safety hazard if required for emergency egress from the building.

Generally, factors such as general age of the building element and a lack of maintenance are the usual causes for this type of defect.

The windows may have several causes, ranging from minor defects as outlined above through to major structural issues, such as damage and/or subsidence (sinking) to subfloor structures.

Where window binding/jamming/out of level appears to indicate major structural issues, a registered builder and/or re-stumping company or concrete slab subsidence expert should be appointed to provide an estimate on the cost of rectification.

For minor causes of repair, replacement where window hardware or frame may be required, as well as minor repairs and cleaning a carpenter, registered builder, window specialist/ company or general handy person will be required to repair the affected windows.

Windows MUST function as a safety requirement and we HIGHLY RECOMMEND that you engage an appropriate professional as soon as possible to check all windows to the property.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.



Serious Safety Hazard 1.07

Location: Windows - Internal Areas

Finding: Window - Handles / Locks / Accessories- Broken

The handle / lock to certain windows was missing / broken at the time of the inspection to many areas of windows.

Absence of the handle / locks limits the operation of the window and may pose as a safety risk as windows do not lock, also window locks not functioning smoothly also poses a safety concern.

Replacement of the handle /locks should be conducted as soon as possible. A general handy person, window manufacturer and/or service technician should be appointed to perform these works to improve the operational state of the affected window and improve the safety of the internal area.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.



Serious Safety Hazard 1.08

Location: External Areas

Finding: Asbestos - Suspected ACM Identified On Site.
IMPORTANT: The Australian Standards for Pre-Purchase building inspections (AS 4349.1-2007) does not require Asbestos inspections in a report, however Master Property Inspections trained inspectors add this bonus service, as we feel that Asbestos is a very important topic that our clients should have an awareness of.

Asbestos in the older homes can be in the glue adhesive behind the wall tiles or floor tiles, Asbestos can be behind the wall tiles and floor tiles in relation to the cement sheet or the tile backing.

Asbestos can be in the old wardrobes and cupboard areas, asbestos can be in the flu systems of the old hot water services or heater flu systems. Asbestos can be on the walls or ceilings. Asbestos can be in the eaves in the older homes and the exterior walls of the older homes. Asbestos can be found in the roof space areas in the floor space areas and in the old sheds.

This is only the typical type scenarios in the homes up to 1990 in particular.

Whilst we are including in this report areas that we suspect is Asbestos, it is important to note that this report in relation to asbestos is a GUIDE ONLY and we do not guarantee that there are no other areas at this property that may contain Asbestos (ACM)

Reporting on Asbestos is outside the Scope of this Report. This suspected defect is highlighted as a caution ONLY and is ONLY a guide as asbestos inspections are outside the scope of pre-purchase inspection and reports.

We suspect, based on our experience in the building industry, that there is a higher risk of the identified building element containing asbestos (ACM).

Areas with the red arrows, have a high potential of containing asbestos (ACM). When a red arrow points at a tile for example, the asbestos material may be in the tile, the tile glue and/or the tile backing sheet.

As Asbestos Reporting is outside the scope of this report, we advise that you consider a separate Asbestos Inspection and Condition Audit, which can include the taking of samples for definitive confirmation of the presence of Asbestos.

In the interim, the client is advised to act with caution, especially when considering any damage to building materials general wear and tear renovations extensions demolition and general maintenance activities due to the suspected presence of Asbestos.

PLEASE NOTE : We are able to perform an Asbestos Inspection and Condition Audit, which can include the taking of samples for definitive confirmation of the presence of Asbestos. This inspection as noted above is outside the scope of this inspection but at request of the client we can perform the necessary inspection and take the samples to the laboratory to give you a comprehensive and definitive inspection report, with laboratory results.



Serious Safety Hazard 1.09

Location: Ensuite

Finding: Window Opening - Not Safe/Defective

The ensuite window is opening more than the current building code standards allow. It may be possible that at the time of the building there was no regulations to minimum opening of windows in upstairs areas or windows above a certain height. You can get better clarification on this from your local council or a registered builder or carpenter.

However this is a major safety concern & regardless of whether this was legal at the time of this building being built or not it is still very dangerous to have these openings that are not limited to the openings as a child, small person or somebody through accidental circumstances can fall through the window.

I highly recommend that you engage a window manufacturer or a window manufacturers technician to change the window mechanisms so that they limit the opening of the window as a matter of urgency.



Serious Safety Hazard 1.10


Location: Manhole To Get Into The Roof Space
Finding: Roof Space Man Hole - Access NOT large enough
DIMENSIONS FOR REASONABLE ACCESS AS PER TABLE 3.2 , AS 4349.1.-2007.
Inspection of buildings - Pre-purchase Inspections - Residential buildings.

Area Access hole 400 x 500 minimum.
Crawl Space 600 x 600 minimum.
Height 3.6 m max on a ladder

Re-Inspection is HIGHLY RECOMMENDED once the man hole is made larger, if possible.

By not inspecting the roof space area there can hide an array of defects, without inspection to the roof void area it is impossible to rule out termite activity and/or termite damage and other undetectable issues .

I would treat this manhole area alteration as a matter of urgency, a carpenter or competent handyman can install a new manhole that complies.



Major Defect

Major Defect 2.11

Location: Garden Areas - All Areas

Finding: Garden trees and vegetation / Yakka Trees - Subsidence - Close To Buildings
PLEASE NOTICE THE ATTACHMENT PICTURES TO THIS DEFECT STATEMENT;
H = the height of the tree at its full potential height, not its height today.
D = the distance from the tree to the building at the trees full potential height.
D = varies pending on one tree to 4 trees or more.


Trees and other vegetation can have a significant local effect on drying of soils. Over a number of years, especially during drought conditions, adjacent trees and vegetation may draw excessive moisture from the soils. The opposite may also occur, where swelling of the soil results when the trees decline or are removed.

As the cumulative moisture deficient is reversed, the surface level around the tree (and adjoining subfloor or concrete slab) will rise and expand laterally. This is often damaging to buildings unless the foundations have been strengthened or designed to cope with the effect.

Subsidence can have complex and varying causes, which will influence the required remedial works. It is advised to begin by consulting a structural engineer to determine the required scope of works. This generally includes some form of underpinning, as well as addressing the underlying cause. Consultation with a geotechnical engineer may also be necessary.

A registered builder specialising in re-stumping / structural damage such as major brick cracking would then generally carry out works as advised by an Engineer and/or Geotechnical Engineer.

d = 1.0H (single tree)
d = 1.5H (group of trees)
d = 2.0H (row of 4 or more trees)



A photograph of a brick house with a red arrow pointing to a tree trunk. The arrow is labeled "Tree Trunk". The house has a red brick exterior and a white gutter. A window with a white frame is visible on the left. A white mailbox is mounted on the wall. A tree trunk is visible on the right, and a red arrow points to it from the left. The arrow is labeled "Tree Trunk".



Minor Defect

Minor Defect 3.12

Location: Tiled Areas

Finding: Tiles - Cracked or damaged

Cracking was evident to the tiling at the time of inspection. While the cracking appears to be minor, these areas are frequently exposed to water, allowing potential for water penetration into adjoining sections of walls or flooring.

If left unmanaged, water penetration to these areas may lead to subsequent water damage, which is likely necessitate repair work to affected building elements.

What is important when tiles are cracking is to determine the cause of the cracking, which may be related to the subfloor structure, typical wear and tear and/or poor workmanship. The cause of the tiles cracking must be determined and repaired otherwise the same defect will occur.

A tiling contractor should be appointed to ensure that no further water damage occurs. The re-application of silicone and grouting throughout remaining tile work is also advised, to further protect the area against water penetration.

Where water penetration has led to water damage, appointment of a relevant tradesperson may be required to repair damaged building elements.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





Minor Defect 3.13

Location: Flooring - All Areas

Finding: Sub Floors With Stumps or Brick Piers - Bouncy / Squeaking
The internal flooring in these areas were identified as being bouncy or squeaking at the time of inspection. A bouncy or squeaking floor surface generally presents as a discernible change in level as they are walked across, in noisy or creaking flooring, or in consequent movement of surrounding furniture and fixtures.

Bouncy floors generally indicate that the floorboards or the subfloor structures are coming loose from the joists that they are installed on. Bouncy flooring may also be the result of gaps between flooring and stumps or joist structures, which require packing.

Bouncy flooring may also be the result of gaps between flooring or joist structures, which require packing and/or addition adhesive.

The client is advised to seek quotations for required repairs from a Registered Builder specialising in re-stumping. The potential resolution may range from packing gaps in subfloor structures through to replacement of subfloors stumps and refixing of flooring.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





Minor Defect 3.14

Location: All Areas - Various

Finding: Building Materials & Hardware That Is Worn / Aged and/or Damaged .

This defect stated in this report is not a requirement under the Australian standards for a pre-purchase building inspection, however Master Property Inspections is proud to identify these items for your extended knowledge of the property, but these type of minor items is again not part of a standard building inspection under the Australian Guidelines.

Photos of the Building Materials, are in the photos attached.

This may have been caused by water damage, moisture and/or general wear and tear. Replacement or repair (which ever is appropriate and cost effective) is up to you of the items attached.

Pre-Purchase Inspections DO NOT require us to note in the reports Worn / Aged and/or Damaged materials and repairs are generally at the owners discretion.

Items like worn and damaged kitchens, door handles, damaged floor tiles, painting, etc, again is at the owners discretion.

Items like cracked glass mirrors, cracked glass windows and windows not operation smoothly are defects that should be repaired by the appropriate trades.

It is IMPERATIVE that you engage registered and qualified trades and at the end of there works they must supply certificates, such as an electrical safety certificate, plumbing and gas certificate if the works are electrical or plumbing, but for items such as damaged door handles, painting an experienced carpenter or handyman can sometimes be engaged.







Minor Defect 3.15

Location: All Areas - Various

Finding: Sub Standard Workmanship or Incomplete.

These Defects are of Sub Standard Workmanship or Incomplete and not finished to a tradesmens like manner.

Please discuss these items with your Building Consultant who performed the inspection and report to discuss and clarify.



The installation of these building elements appear to have been completed to a substandard level of workmanship or is incomplete and does not comply with regular building practices or are just visually displeasing.




Unfinished and substandard building works are likely to degrade more quickly and may create potential for secondary defects to associated building elements and surrounding structures, also the workmanship is VERY displeasing to the eye.

Generally substandard repairs or installation are related to poor workmanship, the use of inappropriate materials, or a failure to complete installation to a suitable standard.

Where installation is substandard and/or incomplete, the client should contact the responsible trade to undertake rectification works, which are advised as soon as possible.

The appropriate tradesperson or specialist or handyman should be appointed to complete the various items for repair and organise the appropriate QUALIFIED trades (or not pending on job) to repair and complete the works to illiminate or reduce further deterioration / disfunction.





Minor Defect 3.16

Location: Paint Internal Areas

Finding: Paint / Plaster - Lath and Plaster and/or Hairline - Defects To Doors, Architraves, Walls & Ceilings, ETC.

It appears that the building has had a re paint or at least painted in areas.

There is the possibility that some or many cracks in the plaster or solid plaster may have been covered up and/or repaired, due to the selling of the home ?

There is always the possibility that the cracks in part or full will come back if the repairs have not been professionally done AND/OR the home has movement and/or subsidence continuing to the property.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.

Superficial scuff marks, damaged plaster, holes in walls,missing paint,sub-standard paint work were noted to the internal walls / ceilings and/or architraves as per the photos attached at the time of inspection.

While these minor defects are detracting from the overall appearance of the affected building element, they do not indicate any operational or structural damage.

This degree of surface damage is consistent with general damage, accidents, movement and wear and tear.

These type of minor defects are appearance cosmetics but they can also lead to the development of secondary building defects over time.

Incomplete areas of paint finish, holes in plaster, exposes the area to moisture, potentially accelerating the deterioration of underlying building materials especially in wet areas such as laundrys and bathrooms.

Superficial scuff marks, damaged plaster, holes in walls,missing paint,sub-standard paint work should be sanded back, filled, levelled and painted, as applicable. Where inadequate or missing protection has led to the deterioration of the associated building element, repair and/or replacement of this building element may be required.

A painting contractor,builder, plasterer and/or suitable handy person may be appointed to perform necessary works to aid the appearance of the affected area and to ensure the area is protected against further deterioration.

Wet areas are the main areas that MUST have SUFFICIENT paint coverage to the walls, ceilings and timber work as moisture can deteriorate the areas.

IN ADDITION - IMPORTANT INFORMATION.

This home has Lath and Plaster and/or Hairline Plaster, which is typical for a home of this age.

Lath and plaster is a building process used to finish mainly interior dividing walls and ceilings.

It consists of narrow strips of wood which are nailed horizontally across the wall studs or ceiling joists and then coated in plaster.

In addition to lather plaster, Hair line plaster, like drywall, plaster cracks due to the movement of underlying framing, changes in the structure's interior environment or poor installation. ... However, hairline cracks in plaster walls are easily concealed with a fresh coat of plaster and paint, but also come back consistently over timesavers it is the nature of Lath and plaster.

Working out if (lath and plaster walls & hair line plaster walls or ceilings) is worth fixing, will depend largely on the nature of the project and the amount of money, or work, you are prepared to put in.

Ultimately the decision to repair or replace the (lath and plaster walls & hair line plaster walls or ceilings) is up to you.



Most old buildings with (lath and plaster walls & hair line plaster walls or ceilings) have some or a lot of cracking that may not always be related to the buildings movement.

If you re-block or re-stump your home, cracks in (lath and plaster walls & hair line plaster walls or ceilings) can become, "slabs of plaster" missing, or falling out. The first thing you need to do when assessing (lath and plaster walls & hair line plaster walls or ceilings) for repair, is to see if the wall is "DRUMMY". You do this by tapping on the surface, if it sounds firm it is most likely ok. Areas that sound hollow, or loose, are what is termed, "DRUMMY". These are the areas like this in (lath and plaster walls & hair line plaster walls or ceilings) need to be removed and replaced.

Finishes to (lath and plaster walls & hair line plaster walls or ceilings) generally have many imperfections.

Ultimately an experienced professional can generally put you on the right direction before spending a lot of money on repairing (lath and plaster walls & hair line plaster walls or ceilings)









Minor Defect 3.17

Location: Plaster Internal Areas

Finding: Plaster & Timber Cracking - Damage Category 2 - Noticeable (up to 5mm)
Whilst we may have a photo of damaged paint, or a minor plaster cracking, etc, there may be many more paint/plaster defects and plaster cracking in other areas throughout the property.


Noticeable cracks are a common occurrence as a result of many primary defects. Such causes may include age, general wear and tear, expected building movement, general expansion/contraction of building materials in different weather conditions, and/or minor failings in the installation or application of building materials.


Noticeable cracks may result in minor sticking or jamming of associated doors and windows, which require easement. However, noticeable cracks are easily filled and repaired. A plasterer can be consulted to install an expansion joint at this point to allow for this movement during different weather conditions.

Monitoring of all cracking should be conducted frequently. Always contact a building inspector should cracks widen, lengthen, or become more numerous. Additionally, your building inspector should also be contacted if associated building elements such as doors and windows become more difficult to operate over time.

Relevant tradespeople, such as carpenters, painters and plasterers, should be appointed to perform remedial works, as deemed necessary.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.







Minor Defect 3.18

Location: Caulking / Silicone-All Wet Areas

Finding: Silicon / Caulking To All Wet Area Junctions and Tile Grouting - Missing or Damaged - Internal Areas

It was noted on inspection that sealant and/or tile grout is missing, damaged or inadequate to the tiled wet areas. This may include floor edges, kitchen benches/splashbacks, vanities, bath tub edges, shower areas to the floor and wall tiles, laundry's and all other areas subjected to water or moisture.

Sealant and/or tile grout where missing, damaged or inadequate to the tiled wet areas allows the water to penetrate into the walls and floors which can cause much damage, to the affect were the damage may become a secondary defect and create a conducive environment for termites and/or cause rotting to the timber studs, floor joists and bearers or plaster etc, especially in showers, baths, laundry and the like

Different materials and floor areas move at different rates, generally causing cracking to grout at this point.

A flexible sealant is required to allow for expected expansion and contraction, while keeping the joint water tight and protective of all associated building materials.

A flexible sealant/silicon and tile mortar should be applied to affected areas to prevent any subsequent water damage that is likely to occur.

Regular maintenance and replacement of damaged or missing sealant and tile mortar is highly recommended to the wet areas, as this is a regular wear and tear defect. Sealant and grouting in areas that come into regular contact with water should be maintained for the long term care of the building in the areas required as water damage is one of the main defects in a building that causes the most damage and without sealant and tile grout always being perfect, secondary defects or secondary damages can start instantly.


Whilst in some of the areas there is sealant/silicon , it has become apparent that the sealant has deteriorated and/or is just missing.

Whilst in some of the tile mortar is perfect , it has become apparent that the tile mortar has deteriorated and/or is just missing in other areas.

A sealant specialist, tiling contractor and/or registered builder should be appointed to assess any damage caused by water to the entire internal, sub-floor, walls etc of the building and clean, take off old sealant and tile mortar, then re-seal and re-mortar these works as soon as possible.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.











Minor Defect 3.19

Location: Cabinetry / Wardrobe Doors Internal Areas

Finding: Cabinetry - Loose hinges / Re-adjustment
Several cupboard / wardrobe doors are not level and detract from the operational state of the cabinetry and doors.
Upon further inspection, it was noted that the hinges to the cupboard doors have deteriorated or just need adjustment. This as a result over time that they have just come loose or deteriorated from their original fixing.

To improve operation of the affected doors, a general handyman / cabinetmaker/ carpenter may be appointed to replace the faulty hinges and/or adjust .

Such works should be completed at the discretion of the client, but we do recommend repairs so that there is no further damages to the existing cabinets or cupboards.





Minor Defect 3.20

Location: Doors - Internal Areas


Finding: Door - Striker plate misaligned - Not latching
The striker plate to this door appears to have become misaligned & not latching during operation at the time of inspection and has consequently resulted in the door's operation being compromised.

This is a common defect and is expected in a property of this age, whether being due to substandard installation or general deterioration of the door hardware and sometimes also the associated hinges

Readjustment of the striker plate and/or hinges is recommended at client discretion.

A qualified carpenter or general handyperson may be appointed to perform rectification works as necessary, at client discretion.

If left unattended, further functional impairment is likely to occur.



Minor Defect 3.21

Location: Doors - Internal Areas

Finding: Door stop - Missing

The door stop is missing or is inadequate to stop the door handle from damaging the wall. Although some building elements may seem irrelevant or unnecessary, all building elements play a key role in the operation and function of the overall structure and its performance.

Re-installation or replacement of the door stop is advised as soon as possible to prevent any subsequent damage to the door or associated structures.

A general handyman may be appointed to perform these works at client discretion.



Minor Defect 3.22

Location: Bathroom

Finding: Toilet Pan - Loose

At the time of inspection it was noted that the toilet pan is loose and unstable, this has the potential to create a secondary defect , with plumbing connections / pipes and / or sewage pipes becoming loose and/or broken.

If left unmanaged, the toilet pan could deteriorate further, leading to greater destabilisation and the potential for water leaks to surrounding building elements.

It is highly recommended that a qualified plumber take a look at the toilet , so to determine if there are any other problems and/or concerns with water flow and/or damaged plumbing due to the movement over time.

It is recommended that the toilet pan be refixed to the floor with concrete , fixing screws or silicone and/or a combination of two elements of fixing mentioned .

Works are to be carried out by a licensed plumbing contractor.



Minor Defect 3.23


Location: Ensuite

Finding: Plaster Ceiling Nails - Popping

Numerous popped nails were identified in the internal ceiling at the time of inspection. Nails and screws hold simply by the friction between them and the surface they are applied to. Over time, the nails and screws can back out, which is often a result of general ageing and deterioration of the building structure.

If left unmanaged, the ceiling sheets may become loose and unstable, increasing the rate of deterioration of the internal ceiling and creating potential for the development of secondary defects.

Re-fastening of popped nails will help to maintain the stability of the internal ceiling and associated building elements. Such minor works will also help to improve the appearance of the affected area and secure the ceiling sheets, so as to prevent the onset of ceiling sagging. These works should be performed by a qualified carpenter or plasterer at client discretion.



Minor Defect 3.24

Location: Ensuite

Finding: Water Rott / Water Staining - Timber Skirting & Door Frames
Water Rott / Water Staining was evident in this area or areas at the time of inspection.

Water staining indicates that surfaces have been exposed to excessive moisture / water over time. The minerals and other elements in the water lead to staining, which may graduate to corrosion and deterioration if left unmanaged.

It would appear that water has come particularly from the shower area, generally from damaged silicon, damaged shower screens and /or defective designs with not enough fall in the shower areas. Sometimes it may be a combination of defective items. Particularly silicon should be repaired as soon as possible to stop or reduce further water damage to the building materials, particularly if the floors in addition are timber or the tiles are damaged allowing water to ingress into the floor areas.

Water staining can be indicative of more serious defects, such as plaster damage that has become detached from its fixings and become dangerous not just cosmetic, wood rot, mould, conducive environment for termites and damage to other types of building materials that are concealed or not concealed by other building elements.

Water staining can cause minor damages such as paint staining, timber discolouration, etc or water staining can lead to more serious major structural defects.

It is important to identify the cause of water staining and STOP FURTHER DETERIORATION by the appropriate tradesperson.

Replacement of any broken or damaged structures is advised in particular if the damage has caused secondary defects that have compromised the building structure or safety of any persons.

It is important to identify the correct professional to perform these works, pending on each situation on how minor or major it has become.





Minor Defect 3.25

Location: Ensuite

Finding: Towel Rail - Loose

The Towel Rail was found to be loose at the time of inspection. While not a major operational defect, function can deteriorate and cause further damage to the plaster/tiles if the problem is left unmanaged.

It is advised that the homeowner performs remedial works to re-attach the towel rail to its original fixing.

A general handyperson may be required to perform these works.



Minor Defect 3.26

Location: External Areas

Finding: Paving Exterior Ground - Uneven

Sections of the external paved area are uneven, creating a potential trip hazard. It appears as though the area has been subject to rough installation, or that paving sections have lifted due to movements in the foundation of the property.

Where paving creates a trip hazard, personal injury may ensue if due caution is not taken by all persons within this area.

Re-paving of the area is required as soon as possible to remedy this situation.

Further consultation with a specialist concreter / paver is advised.



Minor Defect 3.27

Location: Perimeter Of Building - Exterior

Finding: Water Leaking & Water Ingress - External Areas

Water leaks were found to be present to the exterior sides, tops and or bottoms of the windows and/or doors and other areas as per the photos attached, such as brick expansion joints and timber and cement sheet junctions above windows , eaves and other areas.

Leaks are generally caused by deterioration of silicon or rubber seals or sometimes just defective workmanship when no caulking as ever been used .

With gaps like these that can be only a few millimeters to be exposed to weather conditions, can cause wood rott internally to the walls create a conducive environment for termites or possibly cause secondary defects the have the potential for structural damage the can be seen or in the walls internally.

Such leaking creates damp conditions in the affected area, causing potential for water pooling and subsequent water damage if left unattended. These conditions may also attract termite attack as already mentioned above, particularly if the area is subject to minimal levels of sun throughout daylight hours.


It is highly advised that a licensed plumber, handyman, builder be appointed to rectify any water leaks that may be present.

These type of areas require a suitable long lasting exterior silicon or caulking to all areas that are exposed.

It is important to note once caulking these areas if water damage is noticeable to windows, timbers, etc, such as wood rott, it is imperative to engage the appropriate trades for replacement or repairs.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





Minor Defect 3.28

Location: Brickwork

Finding: Brickwork / Masonary - Step cracking and minor cracking
There are several cracks and/or step cracking evident throughout the exterior of the property . These cracks are commonly less than 5mm in width.

Although fine cracks are quite noticeable, they are often only considered to be an appearance defect and usually do not indicate any structural damage most of the time. Generally, the cause of a fine crack is indicative of a separation between brickwork and mortar throughout the structure, but single bricks may also show cracks of this nature.

Step cracking, which is similar to other forms of cracking, has a variety of possible causes. However, the most common is the subsidence of adjacent footings.

Step cracking is a relatively common defect, and is most likely to occur adjacent to windows, doors and other openings. Mortar failure in the gaps between affected bricks indicates the stresses and tensions affecting the wall.

Cracking of this nature can generally be repaired with minor filling and should be conducted by a qualified bricklayer and/or registered builder.

Where step cracking is extensive or severe, the client is advised to consult a structural engineer.

Minor step cracking can be used as a warning sign to address factors causing stress to the wall, which can include the effect of surrounding trees, water leaks, soil erosion, or even the presence of reactive soils in the surrounding area.


Always contact a building inspector should cracks widen lengthen or become more numerous.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.









Minor Defect 3.29

Location: Garden Areas - All Areas

Finding: Garden trees - Overhanging and filling gutters
PLEASE NOTICE THE ATTACHMENT PICTURES TO THIS DEFECT STATEMENT;
H = the height of the tree at its full potential height, not its height today.
D = the distance from the tree to the building at the trees full potential height.
D = varies pending on one tree to 4 trees or more.

Once you have read the report, please feel free to contact me at your convenience to discuss the report in detail as I promised you, you can call me as many times as you feel you need to now or in the future as required.
It is very important that you fully understand all aspects of the report.

Overhanging trees often result in excessive amounts of leaf debris accumulating in gutters.

Gutters are a critical part of the building's management of storm water and rain. It is therefore important that they be kept clear to prevent secondary damage to associated building elements, including exterior and interior walls, ceiling linings and any adjoining building elements. Where gutters are blocked, pooling of rainwater is likely to occur, fast-tracking rust and corrosion of the roof plumbing elements.


It is highly advised that all overhanging tree branches be removed as soon as possible to prevent any further damage. Repair and/or replacement of sections of damaged guttering may also be required where the extent of the damage necessitates.


Such works should be performed by the homeowner; however, appointment of a landscape contractor or an arborist may be required. Consultation with a licensed roof plumber is required where guttering has been damaged.

The property is a very high risk for termites as the environments to the property are very conducive with many susceptible areas.

Please read the report carefully and Maintenance to all susceptible and conducive areas is a MUST to minimise the risk of termite and timber pest existence and timber damage.

GENERAL DEFINITIONS OF SOIL STATES	
Code	Description
1	Very good soil - soil with little or no ground movement from erosion changes
2	Slightly eroded soil - soil with only slight ground movement from erosion changes
3	Moderately eroded soil - soil with slight to moderate ground movement from erosion changes
4	Slightly eroded soil - soil with moderate to high ground movement from erosion changes
5	Extremely eroded soil - soil with severe ground movement from erosion changes
6 to 9	Other soil
10	Soil which is not suitable for building - soil which is not suitable for building due to its condition, location, or other factors which make it unsuitable for building







Minor Defect 3.30

Location: Timber Work - All External Areas

Finding: Timber, exposed to weather / External painting deteriorated
Much of the external paint work including but not limited to windows, fascias, guttering, veranda and other external fitments have been neglected and require attention to prepare and re paint.
External timbers that are frequently exposed to harsh weather conditions require adequate protection (paint) in order to maintain their condition. Where timbers have not been painted or treated adequately, general deterioration is likely to occur at an accelerated rate.

Also

Whilst incomplete or missing paint finish is generally an appearance defect, it can also lead to the development of secondary building defects over time. Incomplete areas of paint finish exposes the area to moisture, potentially accelerating the deterioration of underlying building materials.

Degraded paint finishes should be sanded back, filled, leveled and painted, as applicable. Where inadequate or missing paint protection has led to the deterioration of the associated building element, repair and/or replacement of this building element may be required.

If left unattended, replacement of these timbers is likely to be necessary in the short-term future. Adequate treatment of these timbers is required as soon as possible by a painting contractor should be appointed as soon as possible to perform necessary works to aid the appearance of the affected area and to ensure the area is protected against further deterioration. Alternatively, the homeowner following manufacturer instructions may perform these works.

The property is a very high risk for termites as the environments to the property are very conducive with many susceptible areas.

Please read the report carefully and Maintenance to all susceptible and conducive areas is a MUST to minimise the risk of termite and timber pest existence and timber damage.





Minor Defect 3.31

Location: Timber Work - All External Areas

Finding: Fascias - Wood rot

Wood rot was found to be affecting fascias and barges in this area, evidenced by the presence of mould on the surface in some areas.

Wood rot, also known as Fungal Decay, occurs when timbers and other cellulose building materials are exposed to damp conditions on an ongoing basis.

It is likely that this wood rot has developed as a result of faults in the roof plumbing, creating excessive moisture in this areas.

Frequent exposure to rain and other weather conditions also make fascias and barges susceptible to accelerated deterioration.

Early intervention and regular maintenance will prolong the useful life of these building elements. Prior to any works being performed, the cause of the moisture that has created the visible wood rot should be identified and addressed in a suitable manner.

It is advised that a roof plumber be appointed to inspect all roof plumbing and subsequently identify the cause of the wood rot, which may have been caused by blocked gutters, broken roof tiles, deteriorated tile mortar and/or just deteriorated paint.

Replacement of affected fascias and barges may then be a necessary step in protecting surrounding building elements from such deterioration.

A qualified plumber may be appointed to assess the cause of excessive moisture and to provide advice on any remedial works as required. A qualified carpenter or registered builder may also be required to replace affected building materials.



Minor Defect 3.32

Location: Windows - External

Finding: Windows - Wood Rot

Wood rot was found to be affecting external windows. Wood rot, also known as Fungal Decay, occurs when timbers and other cellulose building materials are exposed to damp conditions on an ongoing basis.

It is likely that this wood rot has developed as a result of frequent exposure to rain and other weather conditions. It is suspected that failure to maintain the window frames over a prolonged period has resulted in them deteriorating at an accelerated rate, increasing their susceptibility to the development of wood rot. Leaks in roof plumbing or associated pipework may have also contributed to the formation of the wood rot in this area.

Early intervention and regular maintenance will prolong the useful life of these building elements. Prior to any works being performed, any associated pipework or roof plumbing should be inspected by a licensed plumber for faults or leaks.

Repair and/or replacement of affected window frames may be a necessary step in protecting surrounding building elements from such deterioration. Remedial works should be performed by a qualified carpenter or registered builder as soon as possible to prevent any further damage.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





Minor Defect 3.33

Location: Lintels - Above All Exterior Openings.

Finding: Lintels - Rusted / Corroded

Severe rusting to lintels can create severe secondary defects, especially when the rust has corroded right into the lintel and in cases such as severe rust a structural engineer may be required to assess the damage.

As surface rust provides no protection to the underlying iron, the deteriorating condition is likely to worsen if not addressed in the short-term future.

Where possible, the use of galvanised (treated) metals or aluminium coated metals aid in rust prevention, as does regular general maintenance. Rust formation can be controlled with coatings, such as paint, that isolate the iron from the environment.

Rusting and corrosion should be managed by ideally removing or limiting the affected surface from exposure to moisture.

A registered builder may be appointed to replace any building elements that have been severely affected by rust or water damage.



Minor Defect 3.34

Location: Roof Areas & Stormwater

Finding: Eaves - Sagging / Damaged / Damp

Sagging to the eaves was evident and visibly poor condition as stated in this report at the time of inspection. This type of defect is generally consistent with older properties, where the eave sheeting has worn over time and the damage may have been sustained as a result of a number of possible causes, including poor roof drainage, leaking roof plumbing, blocked gutters which creates back flow of water into the roof and/or minor impact damage. .

Eaves are important in preventing water ingress to associated walls by promoting adequate water run-off from roofing structures. Their secondary function is to prevent shelter to adjoining structures from excessive moisture and hence prevent water damage to these areas.

Sagging eaves are susceptible to the attraction of excessive moisture, and are therefore considered non-functional. This defect also detracts from the overall appearance and condition of the roofing structure and any associated structures.

A roofing plumbing or general handyman is recommended to perform rectification works as soon as possible. Subsequent water damage is likely to result over time if left unattended.

Where eaves show moderate to severe damage, remedial works may be required. Where water damage is suspected as being the underlying cause, appointment of a licensed plumber is advised as a matter of urgency to identify the source of the water leak.



Minor Defect 3.35

Location: Roof Areas & Stormwater

Finding: Roof plumbing - Flashing inadequate

Some sections of the roof are missing or have inadequate roof flashings. Flashings are metal and other materials which are applied to seals and intersections between roof coverings and building elements.

They are designed to aid in weatherproofing of roof joins.

Flashings that are not installed adequately or are missing are likely to result in water penetration to the interior of the property, as well as creating excessively damp conditions against the exterior surfaces and around the base perimeter of the building.

Premature ageing and secondary building defects are imminent where roof plumbing is missing or inadequately installed. Additionally, water pooling also creates an environment that is susceptible to termite and pest infestation.

A roofing plumber should be appointed as soon as possible to install relevant roof plumbing materials, ensuring that no further damage is sustained.

Some sections of the roof are missing or have inadequate roof flashings. Flashings are metal and other materials which are applied to seals and intersections between roof coverings and building elements.

They are designed to aid in weatherproofing of roof joins.

Flashings that are not installed adequately or are missing are likely to result in water penetration to the interior of the property, as well as creating excessively damp conditions against the exterior surfaces and around the base perimeter of the building.

Premature ageing and secondary building defects are imminent where roof plumbing is missing or inadequately installed. Additionally, water pooling also creates an environment that is susceptible to termite and pest infestation.

A roofing plumber should be appointed as soon as possible to install relevant roof plumbing materials, ensuring that no further damage is sustained.



Minor Defect 3.36

Location: Side Of Building

Finding: Brickwork - Deteriorated mortar - Minor

The mortar is deteriorating, into the brick mortar joints, however at this stage, it does not appear to be deteriorated at a level that is a structural concern.

This generally occurs as when the building was built, the bricklayers used to put a special chemical adhesive into the brick mortar mix as a waterproof, however it is now become apparent that over time on some homes the chemicals are eating into the brick mortar and this will continue in some cases, so I highly recommend that this item be monitored over time by an appropriate and competent person.

Mortar, or 'bedding', is the material which fills joins and intersections between bricks in masonry walls and structures. Sections of mortar in this brickwork were identified as having deteriorated, which is generally expected for a property of this age and condition.

Mortar may deteriorate as a result of age of building materials, minor movement of bricks, or frequent exposure to weathering. Mortar should be replaced to ensure that bricks remain in their intended location and to prevent gaps, which would allow water or moisture ingress and secondary damage as a result.

Mortar deterioration can be addressed by a bricklayer where areas of deterioration are localised and easily accessible. Alternatively, appointment of a registered builder is advised, to repoint large areas of decaying mortar.

Where secondary structural defects have become evident, consultation with a structural engineer may be required.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.







Additional comments

IMPORTANT:

When you find this statement BELOW in the defects statements and/or findings in this report, it is important to further look for this item throughout the entire property for further areas of concern.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.

For your information

For your information 4.37

Location: For Your Information

Finding: General Site Photos
General site photos and other areas of interest are provided for your general reference.





For your information 4.38

Location: For Your Information

Finding: Gas & Electrical Appliances - Inspection & Servicing
For you information

All gas appliances need to be serviced and maintained in good order. Plumbing inspections are outside the scope of the building inspection and must be conducted by a Licensed and registered Tradesperson. It is highly recommended that the client makes immediate arrangements to have the gas appliances checked by a licensed gas plumber to ensure that the appliances are working safely and efficiently.

We recommend that all other installations should also be checked.

Whilst we note and comment of visually apparent defects that are present during the building inspection, legislation requires the checking and documenting of compliance for plumbing requirements be done by licensed plumbers respectively to ensure they are functioning correctly.

It is highly recommended that a registered plumber is required to inspect all the gas appliances and the gas Installation for defective workmanship and for carbon monoxide leaks and/or gas leaks.

For your information 4.39

Location: For Your Information

Finding: Electrical - A further Electrical Invasive Inspection recommended.
Reporting on Electrical wiring and electrical installations to this property is outside the Scope of this Report as Under the Australian Standards for prepurchase building inspections (AS 4349.1-2007) does not require our inspections to cover electrical, however electrical wiring and installation is a very important safety concern and/or hazard. Master Property Inspections Building Consultants are very competent and are guided by the owner of the company, Les Camilleri as he is a registered A grade electrician with a electrical contractors license.

As we ONLY perform a VISUAL ELECTRICAL DEFECT INSPECTION.

It is highly recommended that an invasive electrical inspection take place by a qualified electrician as our inspection is Visual ONLY.

For example we highly recommend that further tests to determine that the main earthing system and the earthing to all metal fittings such as lights etc are all connected.

Upon any Electrical Installation or repairs a certificate of Electrical safety for prescribed or non-prescribed electrical installation work must be given to the owner of the building. (Electricity safety act 1998, Electricity safety (Installations) Regulations 2009)

For your information 4.40

Location: For Your Information

Finding: Advice Summary / Special Notes

This report contains a list of a number of defects that in our judgement require rectification.

Scope

Our engagement is confined to that of a Building Consultant and not that of a Building Surveyor as defined in the Building Act, of 1993. Nor have we checked the title boundaries, location of any easements, boundary setbacks, room dimensions, height limitations and or datum's, glazing, alpine and bush-fire code compliance, or any other requirements that is the responsibility of the Relevant Building Surveyor, unless otherwise specifically noted within this report.

For your information 4.41

Location: For Your Information

Finding: Sub-Floor, No Access - No Man Hole.

It is important to note that there is a manhole to the rear of the home to get to the subfloor area however that subfloor area does not get you to the original part of the home.

The subfloor had NO access point to under the house and in addition a minimum of 600mm high is required under the home for a person to go under the sub floor.

DIMENSIONS FOR REASONABLE ACCESS AS PER TABLE 3.2 , AS 4349.1.-2007.
Inspection of buildings - Pre-purchase Inspections - Residential buildings.

Area Access hole 400 x 500 minimum

Crawl Space 600 x 600 minimum

Height 3.6 m ladder max on a ladder.

By not inspecting the sub floor area there can hide an array of defects, without inspection to the roof void area it is impossible to rule out termite activity and/or termite damage and other undetectable issues .



For your information 4.42

Location: The Site

Finding: Safety Switch Installed-Electrical Polarity On The Electrical Installation And Power Point Tests.
Polarity Testing
What is electrical polarity?
Polarity in electrical terms refers to the Positive or Negative conductors within a d.c. circuit, or to the Line and Neutral conductor within an a.c. circuit.

What is a polarity test?

Since a.c. installations consist of a Live and a Neutral conductor, it is extremely important that these conductors are connected the right way around, within all electrical accessories such as wall sockets or plugs. To ensure this, polarity test is done at each relevant point.

The test instrument should indicate full voltage (230V) between Line-Neutral and Line-Earth conductors. No voltage should be detected between Neutral-Earth.

IN ADDITION FURTHER TESTS AS BELOW.

Electrical Polarity On The Electrical Installation And Power Point Tests.

1/ A polarity test , which tests that the Active , Neutral and Earth wires are connected correctly to the power point terminal connections.

This test clarifies that the electrical installation does have Active , Neutral and Earth as well as correct connections.

2/ Fault Loop Impedance Test , This test is done between Active Conductors and Earth. To test that the loop impedance is below the satisfactory standard.

So in short if there is a electrical fault (in a appliance and/or faulty wiring) the safety switch will trip (operate) within the Australian Standards (AS) regulated interval.

3/ Safety Switch test to trip the safety switch at less then 30 milli amps was performed.

These tests all passed the AS 3000 requirement and exceptance level.

Note : Reporting on Electrical wiring and electrical installations to this property is outside the Scope of this Report as Under the Australian Standards for prepurchase building inspections (AS 4349.1-2007) does not require our inspections to cover electrical, however electrical wiring and installation is a very important safety concern and/or hazard. Master Property Inspections Building Consultants are very competent and are guided by the owner of the company, Les Camilleri as he is a registered A grade electrician with a electrical contractors license.



For your information 4.43

Location: The Site

Finding: Smoke Detectors Battery Replacement.
This inspection DOES NOT test operation of smoke detectors .

Upon moving into a new property, it is highly recommended that the batteries to the smoke detectors all get replaced instantly.

Smoke detector batteries should be replaced every 12 months at a minimum.

It is highly recommended that replacement dates of the batteries be kept in a log book.

Also

Testing of smoke detectors is required monthly.



For your information 4.44

Location: Shower Base - Drummy

Finding: Shower Base - Drummy.

The shower base appears to have been installed defectively and/or water or moisture has made ingress under the tiles.

The base is not solid and when you stand on them you can feel the shower bases moving and crackling and when you tap the bases you can hear the hollow sounds that my experience tells me that the bases are Drummy (not solid)


The term `drummy` refers to the shower base becoming detached from their fixing.

Such defects are generally caused by physical or moisture damage to the area. Drummy shower bases may also be a direct result of poor workmanship during the construction process.

Drummy tiles particularly in wet areas, requires to be addressed as this can lead to further problems, such as wood rott, to the frame or subfloor and can create a very conducive environment for termites.

Specialist trades are available for these types of services.

A registered builder may be required to undertake works if damage is extensive or if secondary building defects have resulted. Otherwise, it is advised that a suitable trade be appointed to perform works as necessary. Immediate action is recommended to ensure that no further damage is sustained in the affected area.



For your information 4.45

Location: Flooring - All Areas
Finding: Flooring Levels—Acceptable
DIGITAL ELECTRONIC FLOOR LEVELLING ASSESSMENT.

NOTE :

THE PHOTOS WITH THE BLUE ARROWS INDICATE THE REFERENCE POINTS, WHICH DETERMINES IN MILLIMETRES IF THE OTHER LOCATIONS WITH RED ARROWS ARE HIGHER OR LOWER THEN THE REFERENCE POINT WITH THE BLUE ARROWS. THERE SHOULD NOT BE MORE THEN 10mm DIFFERENCE IN HEIGHT IN ANY ONE ROOM OR NOT MORE THEN 20mm ACROSS THE ENTIRE HOME AS PER Australian Standard® Inspection of buildings, Part 1: Pre-purchase inspections— Residential buildings AS4349.1-2007.

THIS PROPERTY INDICATES THAT THE FLOORING LEVELS ARE WITHIN THE AUSTRALIAN STANDARDS - Australian Standard® Inspection of buildings, Part 1: Pre-purchase inspections— Residential buildings AS4349.1-2007.

We have taken photos of some areas whilst checking the floor levels to demonstrate our process, however at the time of the inspection, we had taken floor levels through out the building . The photos are just for you information and as a guide only.

At the time of the inspection it appears that the subfloor structure flooring is within standards and tolerances.

Whilst there are some areas that are close to the levels that are not acceptable, generally older homes do have these type of levels, which are due to ground movement, ground change and timber shrinkage.

We advise that the flooring be closely monitored to identify any movement over time. Where flooring remains relatively unchanged for an extended period of time (i.e. several months or seasons) it is likely that the flooring is relatively stable, however unexpected movement of the foundations of the property can happen at any time.









For your information 4.46

Location: Perimeter Of Building - Exterior

Finding: Drainage - Inadequate and/or Perimeter Building Ground Fall Defective.
At the time of the inspection it was noted that the surrounding perimeter soil does not fall away from the slab / building.

Water pooling near foundations and footings is a serious concern with the potential to adversely impact on the longevity of the dwelling. The Building Code of Australia (BCA) outlines that the soil or concrete must be graded away from the dwelling at a minimum of 50mm over 1m (1:50 fall).

The site drainage in this report was found to be inadequate at the time of inspection, creating potential for subsequent water damage to associated building elements, such as foundation subsidence, brickwork cracking, windows and doors moving, concrete paths cracking, etc.

It is important that water does not lie against the base of walls; surrounding paths and ground levels should be sloped to drain water away from walls of the building. Downpipes should not disgorge stormwater onto lower walls or plinths. Stormwater should be carried away by large, regularly cleaned drains.

Ground levels may need to be lowered, re-levelled and/or falls in various directions with drains installed, which can be achieved with concrete or ground soils, etc.

Where site drainage is inadequate, another option can be installation of an Agricultural (Aggie) Drain may be required or more serious remedial works.

These drainage concerns in this report can have grave potential for foundation subsidence and/or secondary damages such as structural defects such as brick movement / cracking as already mentioned above.

It is highly recommended that a plumber, builder and other forms of professionals be appointed to further inspect the area and to install / repair adequate drainage equipment where necessary.

If secondary damages have ALREADY accrued we highly recommend that you engage a structural engineer, geotechnical engineer to start with to then engage a registered builder, qualified plumber to further inspect the property and perform any remedial works as necessary.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.

INFORMATION BELOW AS A GUIDE.

Surface water drainage


Surface water must be diverted away from Class 1 buildings as follows:

(a) Slab-on-ground — finished ground level adjacent to buildings:
the external finished surface surrounding the slab must be drained to move surface water away from the building and graded to give a slope of not less than

- (i) 25 mm over the first 1 m from the building in low rainfall intensity areas for surfaces that are reasonably impermeable (such as concrete or clay paving) or
 - (ii) 50 mm over the first 1 m from the building in any other case.
- (b) Slab-on-ground — finished slab heights:
- the height of the slab-on-ground above external finished surfaces must be not less than
- (i) 100 mm above the finished ground level in low rainfall intensity areas or sandy, well-drained areas; or
 - (ii) 50 mm above impermeable (paved or concreted areas) that slope away from the building in accordance with (a); or
 - (iii) 150 mm in any other case.

In relation to termites Defective drainage and falls create high water and moisture which creates a very high risk for termites as the environments to the property are very conducive with many susceptible areas.

Please read the report carefully and Maintenance to all susceptible and conducive areas is a MUST to minimise the risk of termite and timber pest existence and timber damage.





For your information 4.47

Location: Subfloor
Finding: Subfloor stumps – defective installation

The packers on top of the stumps to the subfloor area do not comply with current building codes. Any Packers should be a non-compressible material.

I highly recommend that you engage A registered builder to determine the works that are required In relation to this matter.



Conclusion

Your attention is drawn to the advice contained in the Terms and Conditions of this Report including any special conditions or instructions that need to be considered in relation to this Report.

In the opinion of this Consultant:

The incidence of Major Defects in this property in comparison to the average condition of similar buildings of approximately the same age that have been reasonably well maintained was considered:

Average

The incidence of Minor Defects in this property in comparison to the average condition of similar buildings of approximately the same age that have been reasonably well maintained was considered:

Average

In conclusion, following the inspection of surface work in the readily accessible areas of the property, the overall condition of the building relative to the average condition of similar buildings of approximately the same age that have been reasonably well maintained was considered:

Average Condition With Repairs Required

Building consultant's summary

Note : The Australian Standards for

prepurchase building inspections (AS 4349.1-2007) does not require our inspections to cover items such as footings belowground, concrete slabs belowground, concealed plumbing, appliances such as air-conditioners, ovens and the like, carpet, quality of paint and typical paint defects, fixtures and fittings, mirrors and all other typical minor defects to the interior of the home and the exterior of the home including landscaping.

In saying the above, we are proud to say that we go over and above in our inspections & reports to provide information on certain items above or not listed for a better understanding of the property.

The condition of the building when compared to similar buildings of its type and similar age in the immediate area and/or other areas, appears to be in AVERAGE condition .

There are a number of defects listed in this report which will require attention to rectify and comply with Australian Standards, to prevent further deterioration / damage to the property as listed in this report.

Minor defects such as paint quality, plaster quality, damaged or worn items / materials can be repaired at your discretion, however minor defects such as caulking, silicon and water related damage should be repaired at your very earliest convenience to prevent and/or stop any damages or further damages. Major defects, major structural defects and safety hazards should all be attended to as a matter of urgency, to prevent further deterioration to the building and provide safety to yourself and all occupants that come with in the building and within the area of the building.

=====

Please Note :

Timber pest damage WAS FOUND on the property and further information is in the report.

The property is a HIGH risk for termites as the environments to the property are very conducive with many susceptible areas as noted in this report.

I can not stress how important it is to reduce and keep clean the trees, vegetation, timber and/or all other debris and all other items not only around the home but to the entire property as a matter of urgency to reduce the very high risk for termite activity and to keep the environment as low risk as possible for a conducive and susceptible area or areas for termites and timber pests.

It is impossible to identify all areas for termites, timber pest and timber pest damage, however keeping the garden clean, dry and taking away all mulch, mulching, bark and heavy and over grown areas will certainly reduce the risk and help identify termite evidence.

Please read the report carefully and Maintenance to all susceptible and conducive areas is a MUST to minimise the risk of termite and timber pest existence and timber damage.

As there appears to be NO termite timber pest control system, the client is HIGHLY RECOMMEND gaining further advice from a licensed pest controller as to the costs and procedures involved with application of a termite management system and/or eradication treatment which should be treated as HIGH PRIORITY.

Asbestos-Information

Asbestos in the older homes can be in the glue adhesive behind the wall tiles or floor tiles, Asbestos can be behind the wall tiles and floor tiles in relation to the cement sheet or the tile backing.

Asbestos can be in the old wardrobes and cupboard areas, asbestos can be in the flu systems of the old hot water services or heater flu systems. Asbestos can be on the walls or ceilings. Asbestos can be in the eaves in the older homes and the exterior walls of the older homes. Asbestos can be found in the roof space areas in the floor space areas and in the old sheds.

This is only the typical type scenarios in the homes up to 1990 in particular.

Master Property Inspections can offer further asbestos sampling and testing, once you own the property.

Asbestos-Suspected ACM Identified on Site.

IMPORTANT: The Australian Standards for Pre-Purchase building inspections (AS 4349.1-2007) does not require Asbestos inspections in a report, however Master Property Inspections trained inspectors add this bonus service, as we feel that Asbestos is a very important topic that our clients should have an awareness of.

Whilst we are including in this report areas that we suspect is Asbestos, it is important to note that this report in relation to asbestos is a GUIDE ONLY and we do not guarantee that there are no other areas at this property that may contain Asbestos (ACM)

Reporting on Asbestos is outside the Scope of this Report. This suspected defect is highlighted as a caution only. We suspect, based on our experience in the building industry, that there is a higher risk of the identified building element containing asbestos (ACM).

As Asbestos Reporting is outside the scope of this report, we advise that you consider a separate Asbestos Inspection and Condition Audit, which can include the taking of samples for definitive confirmation of the presence of Asbestos.

In the interim, the client is advised to act with caution, especially when considering any damage to building materials general wear and tear renovations extensions demolition and general maintenance activities due to the suspected presence of Asbestos.

PLEASE NOTE : We are able to perform an Asbestos Inspection and Condition Audit, which can include the taking of samples to the laboratory for definitive confirmation of the presence of Asbestos. This inspection as noted above is outside the scope of this inspection but at request of the client we can perform the necessary inspections and take the samples to give you a comprehensive and definitive inspection report.

Summary

SUMMARY INFORMATION: The summary below is used to give a brief overview of observations made in each inspection area. The items listed in the summary are noted in detail under the applicable sub headings within the body of the report. The summary is NEVER to be relied upon as a comprehensive report and the client MUST read the entire report and not rely solely on this summary. If there is a discrepancy between the information provided in this summary and that contained within the body of the Report, the information in the body of the Report shall override this summary. (See definitions & information below the summary to help understand the report)

Timber Pest Report - summary

Evidence of active (live) termites	Not Found
Evidence of termite activity (including workings) and/or damage	Not Found
Evidence of a possible previous termite management program	Not Found
Evidence of chemical delignification damage	Not Found
Evidence of fungal decay activity and/or damage	Not Found
Evidence of wood borer activity and/or damage	Found
Evidence of conditions conducive to timber pest attack	Found
Next inspection to help detect a future termite attack is recommended in	

Due to the level of accessibility for inspection including the presence of obstructions, the overall degree of risk of undetected timber pest attack and conditions conducive to timber pest attack was considered:

HIGH

A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This will involve a separate visit to the site, permission from the owner of the property and additional cost.

Unless stated otherwise, any recommendation or advice given in this Report should be implemented as a matter of urgency.

For further information including advice on how to help protect against financial loss due to timber pest attack see Section G 'Important Notes'.

Significant items

The following items and matters were reported on in accordance with the Scope of Inspection. For building elements not identified in this Condition Report, monitoring and normal maintenance must be carried out (see also Section G 'Important note').

Timber pest attack

ACTIVE (LIVE) TERMITES

Important Note. As a delay may exist between the time of an attack and the appearance of telltale signs associated with an attack, it is possible that termite activity and damage exists though not discernible at the time of inspection.

No evidence was found.

TERMITE WORKINGS AND/OR DAMAGE

No evidence was found.

CHEMICAL DELIGNIFICATION

No evidence was found.

FUNGAL DECAY

No evidence was found.

WOOD BORERS

Item 1.01

Location: Garden Area

Finding: Timber Pest - Damage Identified.

It is suspected that timber pest activity is occurring or has occurred as there appears to be evidence of timber pest damage.

Damage caused by timber pests found in termite and timber pest areas is considered a defect if the termite management system is not installed in accordance with the BCA / NCC and relevant Australian Standards.

Despite no live termite or timber pest activity being identified, previous timber pest damage was found in these areas.

Such damage creates a potential safety hazard, and is likely to worsen and cause further damage to adjoining building materials.

If left unattended, this damage creates an unsafe environment and is likely to lead to the need for major structural works.

A building contractor should be appointed immediately to advise on options to prevent further damage and repair all affected building materials. Until such time, caution should be taken by all people coming into contact with these building elements and this area.

The application of a post-construction chemical termite barrier or other termite / timber pest treatments is highly recommended for all properties, particularly if live termite activity has been found on the site previously. Such barriers are highly effective in preventing termite attack on any timber building elements throughout the property.

A durable notice should be placed in the switchboard unit to indicate current termite barriers. At the time of inspection, it appeared as though no termite management system has been installed, with no evidence to suggest preventative works taking place.

We HIGHLY RECOMMEND the client may consider gaining further advice from a pest controller as to the costs and procedures involved with this application.

It is recommended that obtaining such advice be a short-term priority.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.

The property is a HIGH risk for termites as the environments to the property are very conducive with many susceptible areas as noted in this report.

I can not stress how important it is to reduce and keep clean the trees, vegetation, timber and/or all other debris and all other items not only around the home but to the entire property as a matter of urgency to reduce the very high risk for termite activity and to keep the environment as low risk as possible for a conducive and susceptible area or areas for termites and timber pests.

It is impossible to identify all areas for termites, timber pest and timber pest damage, however keeping the garden clean, dry and taking away all mulch, mulching, bark and heavy and over grown areas will certainly reduce the risk and help identify termite evidence.

Please read the report carefully and Maintenance to all susceptible and conducive areas is a MUST to minimise the risk of termite and timber pest existence and timber damage.

The client IS HIGHLY RECOMMEND gaining further advice from a licensed pest controller as to the costs and procedures involved with application of a termite management system and/or eradication, which should be treated as HIGH PRIORITY.





FREQUENCY OF FUTURE INSPECTIONS

The next inspection to help detect termite attack is recommended in:

Important Note. Australian Standard AS 3660 recognises that regular inspections will not prevent termite attack, but may help in the detection of termite activity. Early detection will allow remedial treatment to be commenced sooner and damage to be minimised.

Conditions conducive to timber pest attack

LACK OF ADEQUATE SUBFLOOR VENTILATION

No evidence was found.

THE PRESENCE OF EXCESSIVE MOISTURE

Item 2.02

Location: The Site

Finding: Wet Areas, Moisture Present - Attract Termites.
Excessive moisture can attract termites and produce conditions that promote termite attack fungal growth and wood decay as Termites are attracted to moisture.

Any areas of a home, for example bathrooms around showers with faulty silicon or caulking, moisture in cupboards from plumbing leaking, wood rotting, constant moisture to timbers, constant wet areas in or around the home all are just examples of areas that we call very conducive to termites and immediate action to keep these areas mentioned and all other areas to the inside and outside of a home and garden dry.

All wet areas must be taken care of to reduce the HIGH risk of termite attraction.

Excessive moisture is generally caused by deteriorated inadequate or missing roof drainage leaking plumbing pipes or fixtures poorly plumbed HWS overflows or condenser units and poor site drainage.

It is highly recommended that all plumbing and drainage fixtures and fittings be maintained regularly in order to prevent excessive moisture being present in the external / internal property.



Item 2.03


Location: Perimeter Of Building - Exterior


Finding: HWS Overflow - Not Connected

The Hot Water System (HWS) overflow was found to be disconnected from storm water draining and is creating excessive moisture in the surrounding area.

These damp conditions can lead to secondary defects such as rot, rust or corrosion of associated building elements, the formation of fungal decay, or even the creation of potential slip hazards. When coupled with poor site drainage, pooling of water may also attract termite activity to this area.

It is highly recommended that a licensed plumber be appointed to connect the HWS overflow in order to prevent such an environment from being created. These minor works should be carried out as soon as possible.





Item 2.04

Location: Perimeter Of Building - Exterior

Finding: Air conditioner - Disconnected overflow

The Air Conditioner (A/C) overflow was found to be disconnected from storm water draining and is creating excessive moisture in the surrounding area.

Such leaking creates an environment which is conducive to an array of defects, including water damage to associated building elements and the attraction of termite or timber pest infestation.

It is highly recommended that a licensed plumber be appointed to connect the A/C overflow in order to prevent such an environment from being created.

These minor works should be carried out as soon as possible.

This excessive water creates a much more conducive environment for termites as well.



Item 2.05

Location: Garden Areas - All Areas

Finding: Garden Beds - Conditions Conducive to Termites
Garden beds were found to be evident in areas of garden areas. These garden beds can include untreated timber, bark, excessive old vegetation and with a combination of moisture from watering hosing can make conditions very conducive to termite activity and termite ingress. It is always important to keep the garden beds as clean as possible and take out excess old bark from the trees, leaves and keep bark mulch to a minimum or better introduce rocks or some item that does not create an conducive environment for termites and hold excess moisture.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





Item 2.06

Location: Roof Areas & Stormwater

Finding: Gutters - Requiring Clean Up And Removal Of Vegetation.
Gutters are a critical part of the building's management of storm water and rain. It is therefore important that they be kept clear to prevent secondary damage to associated building elements, including exterior and interior walls, ceiling linings and any adjoining building elements. Where gutters are blocked, pooling of rainwater is likely to occur, fast-tracking rust and corrosion of the roof plumbing elements.

Unclean Gutters prevent building elements from operating as intended, detracting from the overall function of the affected building elements. Additionally, the lack of general maintenance may lead to the development of more significant defects, such as damage to surrounding building materials.

Blockages should be removed and addressed promptly, as they will lead to the development of secondary building defects. The blockage should be removed as the primary rectification works. Secondly, check for any secondary or concealed damage, and then attempt to address the cause of the blockage to prevent recurrence or any water damage to associated structures.

Depending on the location of the blockage and the building elements affected, a licensed plumber may be required to perform necessary remedial works.

This type of environment creates a conducive environment for termites.
The property is a very high risk for termites as the environments to the property are very conducive with many susceptible areas.

Please read the report carefully and Maintenance to all susceptible and conducive areas is a MUST to minimise the risk of termite and timber pest existence and timber damage.

Immediate clean up is required.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





BRIDGING OR BREACHING OF TERMITE MANAGEMENT SYSTEMS AND INSPECTION ZONES

Item 2.07

Location: Perimeter Of Building - Exterior

Finding: Weep Holes - Bridging Or Breaching Of Termite Barriers Defective.
Bridging is the spanning of a termite barrier or inspection zone so that subterranean termites are provided with passage over or around that barrier.

Breaching is the making of a hole or gap in a termite barrier so that termites are provided with a passage over or around that barrier.

Weep holes in the exterior brickwork of the property are designed to allow condensation that may build up between the brickwork and subsequent timber framework to drain from within the wall hence preventing any deterioration of the timber building elements.

Where weep holes are covered by external ground levels such as paving or garden beds concealed entry is available for termites from these grounds into the brickwork or external wall materials.

Additionally build-up of moisture is likely to occur if weep holes are covered further attracting termite activity to these areas.

It is highly recommended that weep holes are left exposed 150mm from the bottom of the weep hole to the ground level and 75mm from the bottom of the weep hole to the top off concrete paving in all areas throughout the external property.

Therefore if any termite activity leading into weep holes becomes easily detectable during frequent pest inspections.

ALL AREAS should be checked carefully for this defect and attached are a few PHOTO EXAMPLES as a GUIDE.





UNTREATED OR NON-DURABLE TIMBER USED IN A HAZARDOUS ENVIRONMENT

Item 2.08

Location: Garden Areas - All Areas

Finding: Timbers - In ground contact

Any timbers in direct ground contact provide opportunity for concealed termite entry and are likely to be subject to premature rot and decay as the soil retains moisture or damp conditions against the timbers.

When met with excessive moisture timber begins to decay and develop wood rot. Any timbers that are in direct contact with external grounds especially if left untreated or non-durable also provide ingress for subterranean termites into that particular element.

Remove untreated timber that is in direct contact with external grounds. Consider replacement with more durable materials i.e. treated timber or non timber elements.

Frequent pest inspections are advised to readily identify any termite activity in these areas.





OTHER CONDITIONS CONDUCIVE TO TIMBER PEST ATTACK

No evidence was found.

Serious Safety Hazards

No evidence of Serious Safety Hazards were found

For your information

SUBTERRANEAN TERMITE MANAGEMENT PROPOSAL

Item 4.09

Location: The Site

Finding: Termite Management System - NO evidence of installation
The application of a post-construction chemical termite barrier and/or baiting stations or the like is highly recommended for all properties, particularly if live termite activity has been found on the site previously. Such barriers are highly effective in preventing termite attack on any timber building elements throughout the property.

A durable notice should be placed in the switchboard unit to indicate current termite barriers.

At the time of inspection, it appeared as though no termite management system has been installed, with no evidence to suggest preventative works taking place.

The client may consider gaining further advice from a pest controller as to the costs and procedures involved with this application. It is recommended that obtaining such advice be a short-term priority.



Item 4.10

Location: The Site

Finding: Identification Procedures Designed To Help Identify Termite Activity

All areas accessible of the dwelling are checked with particular attention paid to the wet areas which were closely assessed to check for excessive levels of moisture and temperature anomalies.

In attempt to identify the presence of hidden timber pest activity , a variety of techniques are adopted to identify irregularities including, a moisture meter and temperature digital meter assessments for comparison analysis , sounding of timber elements using a device called a " donga" visual assessments of materials affected by moisture or signs of deformity , trails and bridging constructed by termites , irregular and regular shaped holes in timber elements indicating pest destruction.

Termite activity generates high temperatures and this contract is grounds for further investigation.

The moisture content variation was within the acceptable range of 5% to 20%.

Temperature variations were all identified under 25 degrees which is consistent with normal range for building elements in these conditions.

At the time of the inspection there was evidence of (timber pest) damage / activity and visually accessible timber damage caused by termites and / or timber pest.

The levels of moisture in all areas were found to be in the normal range.

As all areas are not able to be inspected due obstructions and limitations, we therefore can not rule out the possibility of concealed timber pest activity.

Wall paneling, wall paper, carpet and fixed cabinetry can obscure termite activity.





PREVIOUS TERMITE MANAGEMENT PROGRAM

No evidence was found.

Conclusion

Your attention is drawn to the advice contained in the Terms and Conditions of this Report including any special conditions or instructions that need to be considered in relation to this Report.

The following Timber Pest remediation actions are recommended:

1. Yes - treatment of Timber Pest Attack is required.
2. In addition to this Report a Subterranean Termite Management Proposal to help manage the risk of future subterranean termite access to buildings and structures is recommended.
3. Yes - removal of Conditions Conducive to Timber Pest Attack is necessary.
4. Due to the susceptibility of the property to sustaining Timber Pest Attack the next inspection is recommended in .

Risk management options

To help protect against financial loss, it is essential that the building owner immediately control or rectify any evidence of destructive timber pest activity or damage identified in this Report. The Client should further investigate any high risk area where access was not gained. It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of conditions conducive to timber pest attack.

To help minimise the risk of any future loss, the Client should consider whether the following options to further protect their investment against timber pest infestation are appropriate for their circumstances:

Undertake thorough regular inspections at intervals not exceeding twelve months or more frequent inspections where the risk of timber pest attack is high or the building type is susceptible to attack. To further reduce the risk of subterranean termite attack, implement a management program in accordance with Australian Standard AS 3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical management system. However, AS 3660 stresses that subterranean termites can bridge or breach management systems and inspection zones and that thorough regular inspections of the building are necessary.

If the Client has any queries or concerns regarding this Report, or the Client requires further information on a risk management program, please do not hesitate to contact the person who carried out this Inspection.

Definitions to help you better understand this report

----- PROPERTY INSPECTION REPORT -----

“Client” The person or persons, for whom the Inspection Report was carried out or their Principal (i.e. the person or persons for whom the report is being obtained).

“Building Consultant” A person, business or company who is qualified and experienced to undertake a pre-purchase inspection in accordance with Australian Standard AS 4349.1-2007 ‘Inspection of Buildings. Part 1: Pre-Purchase Inspections – Residential Buildings’. The consultant must also meet any Government licensing requirement, where applicable.

“Building and Site” The inspection of the nominated residence together with relevant features including any car accommodation, detached laundry, ablution facilities and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth, embankments, surface water drainage and stormwater run-off within 30 m of the building, but within the property boundaries.

“Readily Accessible Areas” Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels or accessible from a 3.6 metre ladder, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. Or where these clearances are not available, areas within the consultant’s unobstructed line of sight and within arm’s length.

“Structure” The loadbearing part of the building, comprising the Primary Elements.

“Primary Elements” Those parts of the building providing the basic loadbearing capacity to the Structure, such as foundations, footings, floor framing, loadbearing walls, beams or columns. The term ‘Primary Elements’ also includes other structural building elements including: those that provide a level of personal protection such as handrails; floor-to- floor access such as stairways; and the structural flooring of the building such as floorboards.

“Structural Damage” A significant impairment to the integrity of the whole or part of the Structure falling into one or more of the following categories:

(a) Structural Cracking and Movement – major (full depth) cracking forming in Primary Elements resulting from differential movement between or within the elements of construction, such as foundations, footings, floors, walls and roofs.

(b) Deformation – an abnormal change of shape of Primary Elements resulting from the application of load(s).

(c) Dampness – the presence of moisture within the building, which is causing consequential damage to Primary Elements.

(d) Structural Timber Pest Damage – structural failure, i.e. an obvious weak spot, deformation or even collapse of timber Primary Elements resulting from attack by one or more of the following wood destroying agents: chemical delignification; fungal decay; wood borers; and termites.

“Conditions Conducive to Structural Damage” Noticeable building deficiencies or environmental factors that may contribute to the occurrence of Structural Damage.

“Secondary Elements” Those parts of the building not providing loadbearing capacity to the Structure, or those non-essential elements which, in the main, perform a completion role around openings in Primary Elements and the

building in general such as non-loadbearing walls, partitions, wall linings, ceilings, chimneys, flashings, windows, glazing or doors.

“Finishing Elements” The fixtures, fittings and finishes applied or affixed to Primary Elements and Secondary Elements such as baths, water closets, vanity basins, kitchen cupboards, door furniture, window hardware, render, floor and wall tiles, trim or paint. The term ‘Finishing Elements’ does not include furniture or soft floor coverings such as carpet and lino.

“Major Defect” A defect of significant magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.

“Minor Defect” A defect other than a Major Defect.

“Serious Safety Hazard” Any item that may constitute an immediate or imminent risk to life, health or property. Occupational, health and safety or any other consequence of these hazards has not been assessed.

“Tests” Where appropriate the carrying out of tests using the following procedures and instruments:

(a) Dampness Tests means additional attention to the visual examination was given to those accessible areas which the consultant’s experience has shown to be particularly susceptible to damp problems. Instrument testing using electronic moisture detecting meter of those areas and other visible accessible elements of construction showing evidence of dampness was performed.

(b) Physical Tests means the following physical actions undertaken by the consultant: opening and shutting of doors, windows and draws; operation of taps; water testing of shower recesses; and the tapping of tiles and wall plaster.”

— — — — — TIMBER PEST INSPECTION REPORT — — — — —

“Timber Pest Attack” Timber Pest Activity and/or Timber Pest Damage.

“Timber Pest Activity” Telltale signs associated with ‘active’ (live) and/or ‘inactive’ (absence of live) Timber Pests at the time of inspection.

“Timber Pest Damage” Noticeable impairments to the integrity of timber and other susceptible materials resulting from attack by Timber Pests.

“Major Safety Hazard” Any item that may constitute an immediate or imminent risk to life, health or property resulting directly from Timber Pest Attack. Occupational, health and safety or any other consequence of these hazards has not been assessed.

“Conditions Conducive to Timber Pest Attack” Noticeable building deficiencies or environmental factors that may contribute to the presence of Timber Pests.

“Readily Accessible Areas” Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels or accessible from a 3.6 metre ladder, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term ‘readily accessible’ also includes:

(a) accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the area is not more than 2 metres from a point with conforming clearance (i.e. 400 mm high by 600 mm wide); and

(b) areas at the eaves of accessible roof spaces that are within the consultant’s unobstructed line of sight and within arm’s length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).

“Client” The person or persons for whom the Timber Pest Report was carried out or their Principal (i.e. the person or

persons for whom the report was being obtained).

“Timber Pest Detection Consultant” A person who meets the minimum skills requirement set out in the current Australian Standard AS 4349.3 Inspections of Buildings. Part 3: Timber Pest Inspection Reports or state/territory legislation requirements beyond this Standard, where applicable.

“Building and Site” The main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees and stumps with a diameter greater than 100 mm and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).

“Timber Pests” One or more of the following wood destroying agents which attack timber in service and affect its structural properties:

- (a) Chemical Delignification - the breakdown of timber through chemical action
- (b) Fungal Decay - the microbiological degradation of timber caused by soft rot fungi and decay fungi, but does not include mould, which is a type of fungus that does not structurally damage wood.
- (c) Wood Borers - wood destroying insects belonging to the order ‘Coleoptera’ which commonly attack seasoned timber.
- (d) Termites - wood destroying insects belonging to the order ‘Isoptera’ which commonly attack seasoned timber.

“Tests” Additional attention to the visual examination was given to those accessible areas which the consultant’s experience has shown to be particularly susceptible to attack by Timber Pests. Instrument Testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed.

“Instrument Testing” Where appropriate the carrying out of Tests using the following techniques and instruments:

- (a) electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements;
- (b) stethoscope - an instrument used to hear sounds made by termites within building elements;
- (a) probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g. bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees; and
- (d) sounding - a technique where timber is tapped with a solid object.

“Subterranean Termite Management Proposal” A written proposal in accordance with Australian Standard AS 3660.2 to treat a known subterranean termite infestation and/or manage the risk of concealed subterranean termite access to buildings and structures.

Terms on which this report was prepared

----- PROPERTY INSPECTION REPORT -----

Service

1. This agreement is between the building consultant (“Inspector”) and you (“Client”). You have requested the Inspector to carry out an inspection of your property for the purpose of preparing a Standard Property Report (“Report”) to you outlining their findings and recommendation from the inspection.
2. The purpose of the inspection is to provide the Client with an overview of the Inspector’s findings at the time of the inspection and advice as to the nature and extent of their findings.

3. This Report has been prepared at the direction of and exclusively for the Client. Details contained within this Report are tailored to the Pre-Inspection Agreement between the Inspector and the Client at the time of the inspection and no other party can rely on the Report nor is the Report intended for any other party.

Scope of the Report

4. This Report is limited to the findings of the of the Inspector at the time of the inspection and any condition of the property which is not within the scope as set out herein or which occurs after the inspection is expressly excluded from this Report.

5. This Report expressly addresses only the following discernible to the Inspector at the time of inspection:

- (a) Major Defects in the condition of Primary Elements including Structural Damage and Conditions Conducive to Structural Damage;
- (b) any Major Defect in the condition of Secondary Elements and Finishing Elements and collective (but not individual) Minor Defects; and
- (c) any Serious Safety Hazard.

6. This Report is limited to the observations and conclusions of the Inspector that were readily observable at the building or site and given the state of property at the time of the Inspection.

7. This Report does not include the inspection and assessment of items or matters that are beyond the Inspectors direct expertise.

Inspection Limitations

8. The Inspection is limited to Readily Accessible Areas of the Building & Site based on the Inspector's visual examination of surface work (excluding furniture and stored items) and the carrying out of Tests.

9. Where the Inspection is carried out on a strata or company title property, the Inspection is limited to the interior and the immediate exterior of the residence inspected. The Inspection does not extend to common property areas and the Inspector will not inspect common property areas.

10. The Inspector's findings do not extend to matters where the Inspector was restricted or prevented from assessing the building or site as a result of:

- (a) possible concealment of defects, including but not limited to, defects concealed by lack of accessibility, obstructions such as furniture, wall linings and floor coverings, or by applied finishes such as render and paint;
- (b) undetectable or latent defects, including but not limited to, defects that may not be apparent at the time of inspection due to seasonal changes, recent or prevailing weather conditions, and whether or not services have been used some time prior to the inspection being carried out; and
- (c) areas of the building or site that were obstructed at the time of the inspection or not Readily Accessible Areas of the Building Site. An obstruction may include a condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth.

Exclusions

11. This Report does not consider or deal with the following:

- (a) any individual Minor Defect;
- (b) solving or providing costs for any rectification or repair work;
- (c) the structural design or adequacy of any element of construction;
- (d) detection of wood destroying insects such as termites and wood borers;
- (e) the operation of fireplaces and chimneys;
- (f) any services including building, engineering (electronic), fire and smoke detection or mechanical;
- (g) lighting or energy efficiency;
- (h) any swimming pools and associated pool equipment or spa baths and spa equipment or the like;

- (i) any appliances or white goods including dishwashers, refrigerators, ovens, stoves and ducted vacuum systems;
- (j) a review of occupational, health or safety issues such as asbestos content, the provision of safety glass or the use of lead based paints;
- (k) a review of environmental or health or biological risks such as toxic mould;
- (l) whether the building complies with the provisions of any building Act, code, regulation(s) or by-laws;
- (m) whether the ground on which the building rests has been filled, is liable to subside, swell or shrink, is subject to landslip or tidal inundation, or if it is flood prone; and
- (n) in the case of strata and company title properties, the inspection of common property areas or strata/company records.

12. Should the Client seek information from the Inspector related to one of exclusions above, that information is to be provided by way of a Special-Purpose Inspection Report which is adequately specified and must be undertaken by an appropriately qualified inspector. Additional information requested by the Client is not included in this Report.

Workplace Safety

13. The Client warrants to the Inspector (including the Inspector's, agents, employees and other personnel) that the Building Site is, to the Client's reasonable knowledge, safe and free of hazardous materials and that no party of the Building site constitutes a dangerous environment or work place safety concern.

Acceptance Criteria

14. The Inspector may compare the building being inspected with a similar building, unless specified otherwise in the Special Conditions or Instructions. The similar building which the Inspector may compare the current building to was, to the best of the Inspector's knowledge, constructed in accordance with ordinary building construction and maintenance practices at the time of construction and as such has not encountered significant loss or of strength or serviceability.

15. The Inspector assumes in their Report that the existing use of the building or site will continue unless specified otherwise in the Special Conditions or Instructions.

Acknowledgments

16. The Client Acknowledges that contents of the Report is subject to the Scope of the Report, Inspection Limitations, Exclusions and Acceptance Criteria. This Report does not include recommendations or advice about matters outside the scope of the requested inspection.

17. Should the Client have any queries or concerns about the purposes, scope or acceptance criteria on which this Report was prepared, all enquiries or concerns are to be discussed with the Inspector within a reasonable time upon receipt of this report.

18. The Client acknowledges that they will take all reasonable steps to implement any recommendation or advice provided by the Inspector in their Report as a matter of urgency specified otherwise.

19. Any further discussions the Inspector following the production of this Report addressing concerns will not be reflected in this Report and as such the Report may not contain all advice or information related to the building or site provided by the Inspector.

20. The Client acknowledges that a visual only inspection restricts the Inspectors capacity to inspect the building or site thoroughly and is not recommended by the Inspector unless an inspection of the Readily Accessible Areas and appropriate tests are also carried out.

21. The Client Acknowledges that in accordance with the Australian Standard AS4349.0 2007 Inspection of Buildings, this Report does not warrant or give insurance that the building or site from developing issues following the date of inspection.

22. The Client acknowledges that the Inspector is not affiliated with Hello Inspections Pty Ltd ACN 620 518 238 ("Hello Inspections") nor is Hello Inspections liable for the content of the Report prepared by the Inspector or any other third party and the Client hereby indemnifies Hello Inspections from all claims, losses and damage arising, either directly or indirectly, from the Report and the Client accepts this document can be presented to a court as a complete bar to any proceedings by the client or its agents or related parties against Hello Inspections. The Client further acknowledges the Inspector is the agent for Hello Inspections solely for the purposes of this clause.

23. The Client acknowledges that Hello Inspections may reproduce the content within this Report for any commercial purpose, including sale of the Report in whole or in part to third parties, provided personal details or information of the Client contained therein are excluded.

— — — — — TIMBER PEST INSPECTION REPORT — — — — —

Service

1. This agreement is between the Timber Pest Detection Consultant ("the Inspector") and you ("Client"). You have requested the Inspector to carry out an inspection of your property for the purpose of preparing a Pre-Purchase Standard Timber Pest Report ("Report") to you outlining their findings and recommendations from the inspection.
2. The purpose of the inspection is to provide the Client with an overview of the Inspector's findings at the time of inspection which includes whether the inspector has identified any Timber Pest issues and advice as to the nature and extent of those findings.
3. This Report has been prepared at the direction of and exclusively for the Client. Details contained within this Report are tailored to the Pre-Inspection Agreement between the Inspector and the Client at the time of the inspection and no other party can rely on the Report nor is the Report intended for any other party.

Scope of this Report

4. This Report is limited to the findings of the Inspector at the time of the inspection and any condition of the property which is not within the scope as set out herein or which occurs after the inspection is expressly excluded from this Report.
5. This Report expressly addresses only the detection or non-detection of Timber Pest Attack and Conditions Conducive to Timber Pest Attack discernible to the Inspector at the time of inspection.
6. This Report is limited to the observations and conclusions of the Inspector that were readily observable at the building or site and given the state of property at the time of the inspection.

Inspection Limitations

7. The Inspection is limited to Readily Accessible Areas of the Building & Site based on the Inspector's visual examination of surface work (excluding furniture and stored items) and the carrying out of Tests.
8. Where the Inspection is carried out on a strata or company title property, the Inspection is limited to the interior and the immediate exterior of the residence inspected. The Inspection does not extend to common property areas and the Inspector will not inspect common property areas.
9. The Inspection is not in respect of a particular type of timber pest. Any analysis of a specific timber pest is to be at the request of the Client in which the Inspector would present their findings in a Special-Purpose Inspection Report separate from this Report.
10. The Inspector's findings do not extend to matters where the Inspector was restricted or prevented from assessing the building or site as a result of:
(a) possible concealment of timber pest attack, including but not limited to, timber pest attack concealed by lack of accessibility, obstructions such as furniture, wall linings and floor coverings, or by applied finishes such as render

and paint;

(b) undetectable or latent timber pest attack, including but not limited to, timber pest attack that may not be apparent at the time of inspection due to seasonal changes, recent or prevailing weather conditions, and whether or not services have been used some time prior to the inspection being carried out;

(c) areas of the building or site that were obstructed at the time of the inspection or not Readily Accessible Areas of the Building Site. An obstructions may include a condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth;

Exclusions

11. This Report does not consider or deal with the following:

(a) any information or advice related to timber pest preventative, treatment, rectification, or maintenance options for an attack by Timber Pests; and

(b) an environmental risk assessment or biological risk associated with Timber Pests (e.g. toxic mould), occupational health and safety issues.

12. Should the Client seek information from the Inspector related to one of exclusions above, that information is to be provided by way of a Special-Purpose Inspection Report or management proposal which is adequately specified and must be undertaken by an appropriately qualified inspector. Additional information requested by the Client is not included in this Report.

Workplace Safety

13. The Client warrants to the Inspector (including the Inspector's, agents, employees and other personnel) that the Building Site is, to the Client's reasonable knowledge, safe and free of hazardous materials and that no party of the Building site constitutes a dangerous environment or work place safety concern.

Acceptance Criteria

14. The Inspector may compare the building being inspected with a similar building, unless specified otherwise in the Special Conditions or Instructions. The similar building which the Inspector may compare the current building to was, to the best of the Inspectors knowledge, constructed in accordance with ordinary timber pest management and maintenance practices that ensure it does not attract or support a timber pest infestation during its life.

15. The Inspector assumes in their Report that the existing use of the building or site will continue unless specified otherwise in the Special Conditions or Instructions.

16. The Inspector does not guarantee or warrant the absence of Timber Pests in their Report. The Client acknowledges that certain species may be more difficult to identify than others or require regular inspection or testing to help monitor infestation of the species or susceptibility of the timber, including but not limited to the following species:

(a) Drywood termites. This species has extremely small colonies and is difficult to detect; and

(b) European House Borer (*Hylotrupes bajulus*). It is difficult to detect an attack or infestation of this species as the galleries of boring larvae rarely break through the affected timber surface.

Acknowledgements

17. The Client acknowledges that the contents of the Report is subject to the Scope of the Report, Inspection Limitations, Exclusions and Acceptance Criteria. This Report does not include recommendations or advice about matters outside the scope of the requested inspection.

18. The Client acknowledges that this Report does not assess the structural integrity of the building or site.

19. Should the Client have any queries or concerns about the purposes, scope or acceptance criteria on which this

Report was prepared, all enquiries or concerns are to be discussed with the Inspector within a reasonable time upon receipt of this report.

20. The Client acknowledges that they will take all reasonable steps to implement any recommendation or advice provided by the Inspector in their Report as a matter of urgency unless specified otherwise.

21. Any further discussions the Inspector following the production of this Report addressing concerns will not be reflected in this Report and as such the Report may not contain all advice or information related to the building or site provided by the Inspector.

22. The Client acknowledges that the Inspector is not affiliated with Hello Inspections Pty Ltd ACN 620 518 238 ("Hello Inspections") nor is Hello Inspections liable for the content of the Report prepared by the Inspector or any other third party and the Client hereby indemnifies Hello Inspections from all claims, losses and damage arising, either directly or indirectly, from the Report and the Client accepts this document can be presented to a court as a complete bar to any proceedings by the client or its agents or related parties against Hello Inspections. The Client further acknowledges the Inspector is the agent for Hello Inspections solely for the purposes of this clause.

23. The Client acknowledges that Hello Inspections may reproduce the content within this Report for any commercial purpose, including sale of the Report in whole or in part to third parties, provided personal details or information of the Client contained therein are excluded.